Work	Ord	er ID	64	291
77 01 11	· ·			

Wednesday, December 01, 2010 1:19:29 PM



Page 1

Item ID: D3852-042 Accept Setup Start Revision ID: Stop Item Name: Rib Assembly Start Qty: 2.00 **Start Date:** 12/1/2010 **Cust Item ID:** Req'd Qty: 2.00 Required Date: 12/8/2010 **Customer:** Reference: Start Run Tooling: Approvals: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool# Reject Tool ID Plan Accept Reject Insp. **Work Center ID** Description **Run Hours** Code **Qty Qty** Number Stamp Draw Nbr **Revision Nbr** D3852 Rev A 100 0.00 Large Fab Large Fab 0.00 Memo Large Fab 1- pick D3166-3 to cut D3852-2 rib (RH) as per dwg D3852 using DT9440 jig 2- drill hole (3/16") in D3852-2 using DT9439 jig and open to finish size as per dwg D3852 3- c'sink hole as per dwg 4- remove identification markings 5- deburr 6- weld D3759-1 bushing as per dwg D3852 A/R ER316 S.S. Rod Batch: 111585

8- deburr hole if necessary

7- grind bushing weld flush as per dwg dwg D3852

Dart Aei	Ospace	Liu							
W/O:			WC	ORK ORDER CHANGE	S		-		
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:							
	R	esolution:	Dispositio	n:	QA: N/C CI	osed:		Date: _	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	n B Sign & Date		cation ion C	Approval Chief Eng	Approval QC Inspector
							,		
		·							

	Ork Order ID 64291 ednesday, December 01, 2010 1:19:29 PM											<u> </u>		Page 2
Revision ID:	D3852-042			Accept							Setup	Start		
Item Name: Start Date: Required Date: Reference:	Rib Assembly 12/1/2010 12/8/2010	Start Qty: 2.00 Req'd Qty: 2.00				Cust I Custo		D:						313 118 1181 1281
Approvals:		n:	Date:	Tooling:		•	-	te:		1	Run	Start Stop		
Sequence ID/ Work Center II 130 QC Quality Control)	Operation Description QC10- Inspect visual per Memo	QS1004- ground welds	Set U Run 1 0.00	Hours	Tool	ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
140 QC Quality Control	÷	QC5- Inspect part comple	eteness to step on W/O	0.00	810	hidos				€0 -0	- 12.		. <u></u>	·

0.00

0.00

Identify as per dwg & Stock Location:

Memo

150

Packaging

Packaging

	1								
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date: _	<u> </u>
	Re	esolution:	Dispositi	on:	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NCI	₹)			
DATE	STEP	Description of NC		Corrective Action Section B			cation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
		,			·				
					.				

Work Order ID 64291

Wednesday, December 01, 2010 1:19:29 PM



Page 3

Item ID:

D3852-042

Accept

Setup Start

Stop



Revision ID:

Item Name:

Required Date: 12/8/2010

Rib Assembly

Start Date:

12/1/2010

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID: Customer:

Reference:

				_	
A	aa	rn	va	ls:	

Process Plan:

Operation

Description

Date: Date: **Tooling:**

SPC (Y/N):

Set Up/

Run Hours

Date: Date: Run Start

Qty

Stop

Sequence ID/

Work Center ID

160

Memo

QC21- Final Inspection - Work Order Release

0.00

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject

Insp. Number Stamp

Quality Control

10/12/08 AS

	1		····										
W/O:			WC	ORK ORDER CHANG	SES					8 mg .			
DATE	STEP	PRO	DCEDURE CHA	NGE	E	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
									-				
Part No	:	PAR #:	Fault Cate	gory:	NCR:	Yes N	o DQ	A :	Date:				
	R	esolution:	Dispositio	n:	QA: N	I/C Clos	sed:						
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR)							
DATE	CTED	Description of NC			tion B		Verific	cation	Approval	Approval			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector			
					-								

Picklist Print

Wednesday, December 01, 2010 1:19:33 PM

Work Order ID: 64291

Parent Item:

D3852-042

Parent Item ame: Rib Assembly



Start Date: 12/1/2010

Required Date: 12/8/2010

Page 1

Start Qty: 2.00


Required Qty: 2.00

Comments:


IPP Rev:A 08-12-02 new issue DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3166-3		Manufactured	No			100	Each	6.4231	0.18	0.378947 SAL) <i>i</i>	10-1	2-0
				Location	<u>l</u>	Loc	<u>Oty</u>	Loc Code					
				WA		6.42307	1053						
					55697	2.1053	E -0 5		_				
					59266	0.0)418						
					60270)265		_				
					61193	0.3	3786		_	. 207	n		
					63063		6		Œ	0,37°	10		
D3759-1		Manufactured	No		••	100	Each	23.0000		Pl 10	0.12	07	
				Location	1	Loc 9	<u>Oty</u>	Loc Code					
				ST084			3						
					56942		3						
				WA			20						
					54072		9		_				
					6387		11		_	7628	716-	~ (S)	


W/O:			W	ORK ORDER CHANC	GES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										-
						ļ				
Part No	:	PAR #:	Fault Cate	egory:	NCR	: Yes	No DQ	۸:	Date:	
	Re	esolution:	Disposition	on:	QA:	N/C Cld	sed:	·	Date:	
NCR:			WORK ORE	ER NON-CONFORM	ANCE	(NCR)			
DATE	CTED	Description of NC		tion B		Verific	ation		Approval	
DAIL	SIEP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspecto
•										
								*		



W/O:			M	ORK ORDER CHA	ANGES					.,	
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							1				
Part No	:	PAR #:	Fault Ca	tegory:	NC	NCR: Yes No DQA: Date:					
Resolution:			Disposit	ion:	QA	: N/C Cld	sed:		Date: _		
NCR:		\	WORK OR	DER NON-CONFO	RMANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action S Initial Action Description			Verification Section C		Approval Chief Eng	Approval QC Inspector	
			Chief Eng	Chief Eng		Date				<u>'</u>	
į.											
		·				<u>.</u> j					
··· •											
	į										
					•						
1	1		l	l .		1	i		1	1	



W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No		PAR #:										
	Res	olution:	Disposition):	_ QA: N/C CI	osed:		Date: _				
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE (NCF	?)						
	T	Description of NC		Corrective Action Secti		Verific	cation	Approval Chief Eng	Approval			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section Section	ion C		QC Inspector			
					,							
								-				
								-				
								·				
									<u></u>			
1			1			1			1			



Dail Mo.	· · · · ·			e e									
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	CEDURE CHAN	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				•				-					
				\$?									
Part No	:	PAR #:	Fault Cate		NCR: Yes	No DQ	A :	_ Date: _					
	R	esolution:	Disposition	n:	QA: N/C CI	osed:		Date: _					
NCR:		V	WORK ORDE	R NON-CONFORMA	NCE (NCR)							
DATE	STEP	Description of NC		ı B	Verific	ation	Approval	Approval					
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector				
									,				
					· ·								
					1. The state of th								
									,				
					!								